# JACKSON COUNTY DEPARTMENT OF PUBLIC WORKS CONTRACT CHANGE ORDER

CHANGE ORDER NO	3(FINAL)	PROJECT Woods Chapel Road
•	Orive y, Kansas 66111	_COUNTY NO. <u>2293</u> FED. AID NO. <u>STP-3470(402)</u>
THIS CONTRACT SHAÏ Description of change: See Attachr	nent A	
Amount this change order (p	ilus) ( <del>minus</del> ) ( <del>no change</del> )	\$ 197.237.68
The contract amount will be		
Amount of all previous	ice	\$ 197,237.68
The change order shall become and by any previous change	me an amendment to the co	ontract and all provisions of the contract except as amended above
CONTRACTOR'S ACCEP		OWNER WATEROVAL
BY Flace	900	BA.
Title CF8		Title County Executive
Date 5/23/20	/	Date July 23, 2012
APPROVAL RECOMMEN	idoloran	APPROVALIAS TO FORM /  W. Atten Chay  County/Counselor
Earl No Chief Engineer	will	ATTEST  Landson County Legislature  Clerk, Jackson County Legislature
	CER	TIFICATION
I hereby certify that there is chargeable and a cash bala be made, each sufficient to		cumbered to the credit of the appropriation to which this contract is ed in the treasury to the credit of the fund from which payment is to hereby authorized.
NA pur lar	ee nant	Manager - Division of Finance 015-1512-8040 15122012 001
	· Pi	MAL APPROVAL
Missouri Department of Transport District Engineer	ation.	Missouri Department of Transportation Division Engineer - Construction

Digitally signed by Dennis Bryant
DN: cn=Dennis Bryant,
o=MoDOT, ou=3H35,
email:dennis.bryant@modot.mo
.gov, c=US
Date: 2012.07.30 13:58:01-05'00'

**FILED** 

JUL 3 1 2012

MARY JO SPINO COUNTY CLERK



## Missouri Department of Transportation

Kansas City District
Daniel Niec, P.E., District Engineer

600 Northeast Colbern Rd. 816.622.6500 Fax: 816.622.6550

1.888.ASK MODOT (275.6636) Lee's Summit, Missouri 64086

July 30, 2012

Mr. Rodger Seidleman Jackson County Public Works 303 West Walnut Independence, MO 64050

Dear Mr. Seidleman:

Attached is one copy of approved Change Order No. 3 Final for Project No. STP-3470 (402), Woods Chapel Road Improvements.

Items 163,166, 167, 168 will be nonparticipating; the remaining items will be participating up to the limits of the federal funds that are available for this project.

If you have any questions, please call me at (816) 607-2105.

Sincerely,

James Bentley

District Construction Liaison

JBB

J:\bentlj\thomam1\Correspondence\Jackson County\Woods Chapel\CoRet#3 Final



ATTACHMENT A Woods Chapel Road Change Order #3 (FINAL)
Jackson County Project # 2293 Federal Project STP-3470(402)

#39 36" RCP Class III 437 If / 491 If 54.00 / \$1	36" RCP Class III 437 If ~ 491 If 54.00 /		80 H / 106 26.00 /	18" CMP (12 Gage ) 163 H / 115 H (48.00) /	#26 4" Concrete Bikepath 12,050 sy 12,233.89 sy 183.89 🗸	6" Asphalt Driveway 400 sy 716.38 sy 316.38	CG-1 Dry Curb 4,631 If ~ 4,673.60 If 42.60 <b>^</b>	CG-1 Curb 22,167 If 22,170 If 3.00 ~	#13 7" Asphalt Base 83,882.00 sy 87,129.00 sy 3,247.00 \( \) \$	#12 2" Asphalt Surface 83,882.00 sy - 86,738 sy 2,856.00 /	Class A Excavation 131,230 cy - 137,411 cy 6,181 /	oval 46,806 sy - 47,342 sy 536 /	PLAN/GO AS-BUILT QUANTITY CHANGE UNIT	Jackson County Florest # ZZoo Florest
													QUANTI Y CHANG	
\$19.44 \ \$63.00 \ \$84.00 \ \$120.50 \ \$159.50 \		,	\$19,44 <b>-</b> \$63.00 <b>-</b> /	\$19,44		\$30.45 \	\$14,75	\$14.75/	\$16.19 \	\$5.90 /	\$3.29	\$2.45 \		
\$3,5/4.82 / \$3,024.00) / \$2,184.00 / \$6,507.00 / \$8,613.00 /	\$3,024.00) / \$2,184.00 / \$6,507.00 /	\$3,574.82 / (\$3,024.00) / \$2,184.00 /	(\$3,024.00)	\$3,5/4.82	3	\$9,633.77	\$628.35	\$44.25	\$52,568.93	\$16,850.40 🖍	\$20,335.49 /	\$1,313.20 .	PRICE	

	:		3. 2" PVC Waterline	2. 4" PVC V	1. Temporar				#168NEW	#167NEW	#166NEW	#33	#77	#75	#72	#70	#64	#3	<b></b>	#60	#56	共50	ITEM NO.
			Vaterline	4" PVC Waterline Relocation	Temporary Pipe Installation	FORCE ÁCCOUNT ITEMS	4		15" Fly-Ash Treated Subgrade	Flared End Section 24" RCP	Flared End Section 15" RCP	Force Account (SEE BELOW)	Wheel Chair Ramps	Eroison Control Blanket	Sediment Removal	Silt Fence	Temporary Seeding	Seeding	Traffic Barrier	Temporary Crushed Rock	Channelizers	Flared End Section - 36" RCP	DESCRIPTION
	·													•	:	٠.	,		-				,
			Lump Sum	Lump Sum	Lump Sum				0 sy	0 ea .	Q ea	\$230,954.12	757.16 sf	0	138.75 cy	19,209 If	14.23 acres	14.50 acres /	2278 If	5,823.73 sy	210 ea	7 ea 🗸	PLAN/ÇO QUANTITY
	:	2 of 3	\$9,372.40	\$18,636.74	\$19,825.00				3,156.33 sy	3 ea	3 ea	\$221,339.85	440 sf	2,133 sy	0 cy	19,257 lf	29.73	24.47 acres	2,480 lf	5,949.23 sy	399 еа	беа	AS-BUILT QUANTIJY
,	:								3,156.33	. დ	ώ	(9,614:27)	(317.16)	2,133	(138.75) 🗸	.48	15,50	9.97 /	202 🖊	125,5 /	189 /	(1.00) 🗸	QUANTITY CHANGE
1	-							TOTAL	\$6.91	\$900.00	\$600.00	Ä	\$41.80	\$3.30 ^	\$27.60 ~	\$1.38 /	\$2,040.00 /	\$2,400.00 /	\$13.20	\$6.50	\$66.00	\$1,510.00	UNIT PRICE
T. T. 11 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1								<b>\$</b> 197,237.68 <b>/</b>	\$21,810.24	\$2,700.00	\$1,800.00	(\$9,614.27)	(\$13,257.29)	\$7,038.90	(\$3,829.50)	\$66.24	\$31,620.00	\$23,928.00	\$2,666.40	\$815.75	\$12,474.00	(\$1,510.00)	PRICE CHANGE

. ..

17.	6.	į,	14.	ᅉ	13	11.	<b>1</b> 0.	ဖ်	ρ.	.7	<b>р</b>	<u>5</u>	4	NO NO NO
Surveying Georgian Drive Waterline	Structure Adjustment (3 total)	Relay Pipe Out of L2-5	Remove & Reset Light Pole	Asphalt Patching	Replace Fence	Storm Sewer Alterations 153+88 & 218+20	Temporary Drive @ 185+00	Flyash Damage Repair	Waterline Damage Repair	Lower 12" Waterline @ Georgian Drive	Added 16" DIP Waterline	Phone Line Relocation	way W	NO DESCRIPTION
Lump Sum	Lump Sum	Lump Sum	Lump Sum	Lump Sum	Lump Sum	· Lump Sum	Lump Sum	Lump Sum	Lump Sum	Lùmp Sum	Lump Sum	Lump Sum	Lump Sum	PLAN/CO QUANTITY
\$276.00	\$1,505.90	<b>\$</b> 468,91	\$2,650.00	\$108,060.84	\$774.53	\$6,948.80	\$2,495.08	\$1,397.25	\$591,73	\$19,859.54	\$13,804.46	\$7,076.50	\$7,596.17	AS-BUILT QUANTITY
		-											•	QUANTITY CHANGE
														UNIT PRICE
									•					PRICE CHANGE

FA TOTAL

\$221,339.85

## MEMO OF EXPLANANATION

#### **CHANGE ORDER #3(FINAL)**

Woods Chapel Road Federal Project STP-3470(402) County Project 2293

#6 Pavement Removal Tying the east end of the project into the existing pavement was not addressed in the plans. This pavement removal was necessary in order to accomplish this tie in. Increased plan quantity by 536 sy for an increase of \$1,313,20.

#7 Class A Excavation The plans indicated there was 3,000 cy of excavation at Woods Chapel & Liggett Road. Before and after cross sections revealed there was 9,181 cy of excavation at this site resulting in an increase of 6,181 cy for an increase of \$20,335.49.

#12 2" Asphalt Surface As-built field measurements and the plan quantity main line pavement matched reasonably. All the overruns in this item are in the side streets and various Park roads. The project was built to the limits shown on the plans. Therefore this overrun is the product of plan error. This results in an increase in this item of \$16,850.40. (3%)

#13 7" Asphalt Base Same reason as above (Item 12). This results in an increase of \$52,568.93.

#18 CG-1 Curb this is a reasonable overrun, and is field measured. Increased contract by \$44.25.

#19 CG-1 Dry Curb The as-bullt quantity is field measured and results in an overrun of 42.6 if ( 0.9% ) this increases contract by \$628.35.

#22 6" Asphalt Driveway This is an overrun of 78.18 sy due to increasing the length of several drives for a smoother transition into the bike path and roadway. This increases contract by \$9,633.77.

#26 Concrete Bikepath This is an overrun of 183.89 sy from Change Order #1 and is the actual field measured quantity. This is an underrun of 54.11 sy from plan quantity, This is an increase of \$3,574.82.

#34 24" CMP This overrun of 26 if is due to plan quantity error. This increase of 26 if results in an increase to the contract of \$2,184.00.

#39 36" RCP Class III This quantity represents the actual field measured 36" RCP installed. This is an overrun of 54 If for an increase of \$6,507.00.

#40 36" RCP Class IV This quantity represents the actual field measured 36" RCP Class IV installed. This overrun of 54 if results in an increase of \$8,613.00.

#49 18" RCP FES Field condition revealed another 2 flared end sections were required, This results in an increase of \$1,300.00.

#50 36".RCP FES The flared end section at Sta. 163+65 Rt. Was eliminated resulting in a decrease of \$1,510.00.

#56 Channelizers 399 channelizers is the final count of this item used through out the project. This project was stalled due to many utility delays. This overrun 189 units results in an increase of \$12,474.00.

#56 Temporary Crushed Rock This is the final measurement of this quantity. Due to utility delays the project went through 2 winters and this rock was necessary to keep residents and Parks roads and driveways accessible. This is ancrease of \$815.75 from Change Order #1.

#61 Traffic Barrier This is the final field verified quantity actually placed. This is an increase of 202 if from Change Order #1 resulting in an increase of \$2,666.40.

#63 Seeding This represents the amount seeding placed on the the project. The plan quantity was in error. This overrun of 9.97 acres results in an increase of \$23,928.00.

#64 Temporary Seeding This is the final amount placed on the project. Through out the life of the project several areas had to be done twice due to additional sidewalk being added to the project and the changing of phases for traffic to keep the road open. This is an increase to the contract of \$31,620.00.

#70 Slit Fence After review of the diaries and quantity book this is the final amount of slit fence installed. This is an increase of 48 if from Change Order #1. This increases the contract by \$66.24.

#72 Sediment Removal This was error on my part in Change Order #1. This item is subsidiary and not a pay item. This results in a decrease of \$3,829.50.

#75 Erolson Control Blanket After Change Order #1 was authorized it was determined to placed erolson control blanket on the west end bank of the project to stabilize this bank. This Increased the contract by \$7,038.90,

#77 Wheel Chair Ramps this final quantity is the amount of ramps placed as measured in the field. This underrun of 317.16 sf results in a decrease to the contract of \$13,257.29.

- V9 #163 Force Account This item decreases \$9,614.27 from Change Order #1. A Memo of Explanation is attached covering all the force account items.
- #166NEW It was determined in the field to add 3 flared end sections to 3 pipe runs. This increases contract by \$1,800.00.
- #167NEW It was determined in the field to add 3 flared end sections to 3 pipe runs. Increases contract by \$2,700.00.
- #168NEW 15" Fly-ash Trated Subbrade. The subgrade just east of Renau Drive required additional stabilization. This increases contract by \$21,810.24.

#### FORCE ACCOUNT MEMO OF EXPLANATION

- 1. Temporary Pipe The design did not allow for drainage of the Phase 1 by-pass therefore creating a pond on the north side of the by-pass ( Sta 183+00 ) This item covers the installation of a temporary pipe.
- 2. The 4" PVC waterline at the Park entrance had to be lowered to avoid conflict with the road construction ( Park main entrance)
- 3. It was requested to install a 2" PVC waterline from the Shelter 2 restroom to the County building at 22301 Woods Chapel.
- 4 6 driveways were widened due to R/W concessions and requests from Lee's Summit. Work-Included curb-removal and concrete widening.
- 5. the phone line on Park property had to be relocated to build new park road. Ranger Station & Maintenance access road
- 6. Design error. Needed to add additional 16" DIP waterline to connect to existing water tower.
- 7. Design error. The new waterline at Georgian Drive was designed too shallow. Therefore during subgrade preparation it hit. This item covers the cost to lower this waterline.
- 8. This is the fee Lee's Summit Water charged Amino to repair damage to the above waterline.
- 9. This covers the cost of reworking the fly-ash subgrade at Georgian Drive damaged by waterline break:
- 10. A temporary drive not shown on the plans was requested to accomdate access to the property at Sta 130+00 Rt.

- 11. These 2 storm sewers had to be altered to fit field conditions
- 12. The fence at Sta 143+00 Lt had to be replaced ( Bromley property ) at Lee's Summit's request.
- 13. The asphalt base, which is not designed to be a surface coarse, was subject to traffic, snow plows, and delcers for 2 years due to utility delays. Various areas exhibited some surface segradation, cracks, and minor pot holes. These areas were milled 2" deep and replaced at cost. (no profit)
- 14. This needed to be done to place additional sidewalk Lee's Summit requested.
- 15. Field design change to avoid new waterline.
- 16. 3 structures has to be adjusted to fit existing and new field conditions.
- 17. This covers resurveying Georgian Drive due to waterline work.